

MARITIME SAFETY COMMITTEE 78th session Agenda item 26 MSC 78/26/Add.2/Corr.1 29 July 2004 ENGLISH ONLY

REPORT OF THE MARITIME SAFETY COMMITTEE ON ITS SEVENTY-EIGHTH SESSION

Corrigendum

Annex 20 to MSC 78/26/Add.2 on Adoption of the IMO unique company and registered owner identification number scheme (resolution MSC.160(78))

Paragraph 6 of the annex to annex 20 is replaced by the following:

- "6 The IMO unique company and registered owner identification number should be inserted on the following documents:
 - .1 Document of Compliance; Safety Management Certificate, Interim Document of Compliance; and, Interim Safety Management Certificate, required by the International Safety Management (ISM) Code;
 - .2 Continuous Synopsis Record required by SOLAS regulation XI-1/5; and
 - .3 International Ship Security Certificate and Interim International Ship Security Certificate, required by the International Ship and Port Facility Security (ISPS) Code."

For reasons of economy, this document is printed in a limited number. Delegates are kindly asked to bring their copies to meetings and not to request additional copies.